



**KEYSTONE  
RV COMPANY**

**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

Safety Recall: 24V-234  
Safety Advisory: 24-452  
May 4, 2024

**IMPORTANT SAFETY RECALL**

MELISSA [REDACTED] & ALAN [REDACTED]  
[REDACTED]  
[REDACTED], WA [REDACTED]

This notice applies to your vehicle: [REDACTED]

Dear MELISSA [REDACTED] & ALAN [REDACTED]:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2021-2023 Montana, 2021-2022 Montana High Country, 2022-2024 Fuzion, 2021 Cruiser, 2024 Aspen Trail LOFT Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided that the vehicles in the recall population with the Suburban stove LED backlight printed circuit boards (PCB) are not fully coated. The lack of adequate coating in the connection passages between the layers of the PCB can allow liquid from the cooktop surface to accumulate which could result in a short circuit resulting in failure of the PCB. If the PCB fails, it can become overheated and the polyethylene cover of the lights can melt and possibly ignite causing a fire.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is that the circuit powering the LED backlights will be cut and properly terminated. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

Owners should disconnect the power to the unit when not in use, and the suburban stove top should not be used until this recall is completed. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1/2 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.nhtsa.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this RV, please call Keystone Customer Service at 1-866-425-4369 or email [recall@keystonerv.com](mailto:recall@keystonerv.com) with your name and VIN.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

cc: National Highway Traffic Safety Administration (NHTSA)

